

# **DRAM CUP HILL**


## **WATER STORAGE TANK RENOVATION**

### **Milford, NH**

- 1960 - Dram Cup Hill, a 500,000 gallon, pre-stressed concrete storage tank was built
- April 15, 2013 - Routine inspection and cleaning was performed by Underwater Solutions Inc.
- July 26, 2013 - As a result of the April inspection, AmTech Tank Lining & Repair Co. of Plymouth, NH was hired to repair the exterior roof spalling and seal-coat the entire exterior roof
- October 31, 2013 - The Town received an approval letter from the NHDES for a low interest State Revolving Loan, 10 years at 1.7000%
- 2014 Proposal - Repair interior roof spalling and reline entire interior surface with a durable poly lining for longevity
- The warrant amount, \$330,000, covers design, engineering, construction and related costs for the Dram Cup Hill water storage tank renovation



*Dram Cup Hill - 500,000 gallon Water Storage Tank*



*Floor With Tight Surface Cracks And Mild Staining*



*Interior Walls With Tight Shrinkage Cracks, Efflorescence And Mild Staining*



*Overhead With Concrete Spall, Exposed Wire Mesh And Tight Surface Cracks*